

Z-AXIS ZERO SETTER

Tool presetter (Z-axis zero setter Z-50) is used in CNC- milling machining centres to set the tool height in reference to the machine table or the workpiece surface. Setting height - 50.00 ± 0.0 mm

ITEM CODE	MODEL NO.
16601	Z-50 (Non Magnetic with Dial)
16602	Z-50 (Magnetic with Dial)

FEATURES/USES

- ◆ Large setting surface of spring loaded plunger for convenience.
- ◆ Pressing force is very low to avoid breakage of small end mill & drill.
- ◆ Easy to calibrate by a ground parallel or gauge block.