
# (100-11 (100-1


# **Thread Gauge profiles**

#### We manufacture the following types of threads:



#### Note

 PF, STI (Wire threads), NPSM, NPSC, NPTR, NPSH, NPSL, NPSF, NPSI, NGT, MJ, UNJF, UNJC, DIN 2999, DIN 158 are some of the other types of threads which we also manufacture.



### Please provide the following information to enable us to send a quote

- · Type of gauge (Thread plug or Thread ring)
- · Thread series (i.e. Metric, Unified, etc.) or thread angle
- · Diameter & pitch/TPI of the thread
- Direction of thread (Right hand or Left hand) (Assumed Right hand if not specified)
- Tolerance class
- · Lead or number of starts (Assumed single start if not specified)




#### **RANGE**

Thread Plugs	0.8 mm to 450 mm
Thread Rings	1 mm to 450 mm
Taper Thread Plugs	1/16 inch to 16 inch (Taper 1:16)
Taper Thread Rings	1/16 inch to 16 inch (Taper 1:16)

# M3 x 0.5 - 6H M4 x 0.7 - 6H M5 x 0.8 - 6H M6 x 1 - 6H M8 x 1.25 - 6H M10 x 1.5 - 6H M12 x 1.75 - 6H

Set of Double ended Metric Thread Plug gauges in an attractive box



#### **MINIATURE**

Nominal diameter	Pitch	Tolerance da	ss
		Thread plug	Thread ring
	METRIC		
M1		5H	6h
M1.1	0.25 mm	5H	6h
M1.2	0.25 mm	5H	6h
M1.4		5H	6h
attini ses	UNIFIED		
1.00 UNM	0.25 mm		
1.20 UNM	0.25 11111		
No.0 (0.060")UNF	80 TPI	2B	2A
	Note: Belo	w 1 mm on re	equest





#### **MULTI START**







#### **HOLE LOCATION**



#### **CUSTOMIZED GAUGES AS PER REQUIREMENTS**



#### Note

 Odd pitch and diameter combination, extra fine pitch gauges also manufactured.



#### **METRIC**








Thread gauge dimensions are as per DIN ISO 1502

# 90° 30° 30° P/2 P

#### **TOLERANCE DIAGRAM INTERNAL & EXTERNAL THREADS**




#### Acceptance criteria for components:

The GO gauge when screwed by hand without using excessive force, should enter and pass the whole length of the workpiece thread. The NOT GO gauge when screwed by hand without using excessive force, should not enter the component by more than two turns of the thread from both ends.


#### UNIFIED



Thread gauge dimensions are as per ANSI/ASME B1.2



#### **TOLERANCE DIAGRAM INTERNAL & EXTERNAL THREADS**



#### Acceptance criteria for components:

The GO gauge when screwed by hand without using excessive force, should enter and pass the whole length of the workpiece thread.

The NOT GO gauge when screwed by hand without being forced, should not enter the component by more than three complete turns.

#### 'G' PIPE





These are pipe threads where pressure-tight joints are not made on threads. Gauge dimensions are as per ISO 228-2.

	Tolerance class
Thread Ring gauge	'A' & 'B'
Thread Plug gauge	-

# P = Pitch


#### Acceptance criteria for components:

The GO gauge when screwed by hand without using excessive force, should enter and pass the whole length of the workpiece thread. The NOT GO gauge when screwed by hand without using excessive force, should not enter the component by more than two turns of the thread from both ends.

#### **ACME & STUB ACME**




- Gauge dimensions for Acme threads are as per ASME B1.5 and Stub Acme as per ANSI B1.8
- Most commonly used class is 2G. If less backlash is desired in acme threads, 3G & 4G class are used
- The height of Acme threads is 0.5p, whereas the height of Stub Acme threads is 0.3p



#### **TRAPEZOIDAL**



- Gauge dimensions are as per DIN 103-9
- Recommended Tolerance classes are 7H/7e for medium tolerance quality and 8H/8c for coarse tolerance quality.






#### **NPT**




Gauge dimensions are as per ASME B1.20.1. Gauges are supplied as Basic Step & Min/Max Step.




#### **GAUGING EXTERNAL TAPER THREADS**

#### With Basic Step Taper Threads Ring Gauge




#### **GAUGING INTERNAL TAPER THREADS**

#### With Basic Step Taper Threads Plug Gauge




The Basic Step gauge when screwed onto the threads of the component by hand, should be flush with the end of the component face within 1 turn, as shown above

#### With Min / Max Step Taper Threads Ring Gauge



#### With Min / Max Step Taper Threads Plug Gauge



When using a Min/Max Step type gauge, the end of the component face should be flush between the Minimum and Maximum steps.




#### **NPTF, ANPT**











L2 Ring

6 Step Crest Check Ring







L1 Plug

L3 Plug

6 Step Crest Check Plug

NPTF threads are also known as Dryseal threads as they do not require a sealant to form a leak-proof joint.

Туре	Standard	Plug gauges	Ring gauges
NPTF	ANSI/ASME B 1.20.5	Thread plug gauges L1 & L3 (Basic Step or Min/Max Step)	Thread ring gauges L1 & L2 (Basic Step or Min/Max Step)
ANPT	SAE AS71051B	6 Step Crest Check Plug	6 Step Crest Check Ring

- · NPTF & ANPT threads require additional gauging as the truncation of these threads should be maintained within specified limits.
- · L1 & L3 plug gauges and L1 & L2 Ring gauges are used in combination to verify the size and taper of the component threads along the thread length.
- · 6 Step Crest check plug and ring gauges are used to verify the crest diameter and truncation of the component threads along the thread length.


#### **TAPER PIPE THREADS ISO 7-R, BSPT, PT**











- These are taper pipe threads where pressure tight joints are made on threads. The thread angle is  $55^\circ$
- Gauges are manufactured as per ISO 7-2, EN 10226, BS 21, JIS B0253



#### ADJUSTABLE THREAD RING GAUGES AND SET PLUGS





Adjustable Thread Ring Gauge



Set Plug






Adjustable Thread Ring Gauge



Set Plug

#### CONSTRUCTION



	From	Up to & including
Metric	M3	M28
Inches	0-80	1

#### Note

- These gauges are ring shaped, but they have a split and an adjusting and locking screw facility to finely adjust their correct gauging size. For setting these gauges, "Setting plugs" are needed.
- Truncated thread set plugs have threads with both truncated and full form threads for both the Go and the Not Go member.
- · The truncated section controls the pitch diameter.
- Use thread setting plug to adjust & set adjustable thread ring gauges.
- A thread ring gauge should be set on the full form portion of the set plug (back portion). The ring
  is then turned onto the truncated portion and should have the same drag and fit as when turned
  through the full form.
- The setting of Adjustable Ring using a set plug involves high skill which is done by Adjusting screw followed by locking screw.
- It is strongly recommended that once the thread ring gauge has passed all the above processes, the locking screw and adjustment screw holes are sealed with sealing wax to prevent any tampering.

#### **TUNGSTEN CARBIDE THREAD GAUGES**

#### **FEATURES**

- Tungsten carbide only for frequently used go-side gauges. NOT GO side in the conventional OHNS Steel material.
- Gauge life 5 to 10 times more than that for similar gauges made from steel.
- Life will vary greatly depending upon the work piece material.



Size	Pitch	ISO (Class)
M1.6	0.35	6H
M2	0.4	6H
M2.5	0.45	6H
M3	0.5	6H
M4	0.7	6H
M5	0.8	6H
M6	1.0	6H
M8	1.25	6H
M8	1.0	6H
M10	1.5	6H
M10	1.25	6H
M10	1.0	6H
M12	1.75	6H
M12	1.5	6H
M12	1.25	6H

# **API (Oil) Thread Gauge**





#### API

**BAKER** has collaborated with KURODA PRECISION INDUSTRIES, a leading Japanese thread gauge manufacturer, to distribute their high quality API thread gauges in India. KURODA has been granted the right of use of API Official Monogram for the following API Thread Gauges since 1957; Specification 5B under the License no. 5B-0015, Specification 7-2 under the License no. 7-2-0187.



#### Kuroda Precision Industries: A Brief introduction

Kuroda was founded in 1925 as one of the first dedicated gauge manufacturers in Japan. Since then, they have developed various products based on precision measuring and processing technology. While working to preserve traditional skills, techniques and reputation for best quality, they also employ latest technologies through active R&D. Kuroda's mission continues to be that of support to the customers through their high precision measuring and processing technology based on the philosophy of P&P (Precision and Productivity) and the spirit of C&C (Challenge and Create).

#### **FEATURES**

- · Light construction
- · Longer operating life
- · Manufacturing to the highest Japanese quality standards
- Best Raw materials from Japan used
- Easy to use: The handle is standard-equipped on all products
- Upon request, a Hook Ring can be mounted on larger diameter ring gauges for better work ability

#### When ordering, please provide information on:

- Type of gauge
- Size of gauge
- Reference master or working gauges
- Plug or ring or both
- Right hand or left hand, in case of API Spec. 7-2 thread gauges
- Inspection results to be stated in inches or mm



# **API (Oil) Thread Gauge**



#### **API SPEC. 5B (Casing & Tubing)**

#### LP

Line Pipe Thread Gauges Thread angle 60°

Size	T.P.I.	Taper
1/8	27	1:16
1/4 3/8 1/2 3/4	18	1:16
%	18	1:16
1/2	14	1:16
₹4	14	1:16
1	11 1/2	1:16
1 1/4	11 1/2	1:16
1 1/2	11 1/2	1:16
2	11 1/2	1:16
2 1/2	8	1:16
3	8	1:16
3 1/2	8	1:16
4	8	1:16
5	8	1:16
6	8	1:16
8	8	1:16
10	8	1:16
12	8	1:16
14D	8	1:16
16D	8	1:16
18D	8	1:16
20D	8	1:16

#### **CSG**

Casing Round Thread Gauges Thread angle 60°

Size	T.P.I.	Taper
41/2	*8	1:16
5	*8	1:16
51/2	*8	1:16
6	*8	1:16
7	*8	1:16
75/8	*8	1:16
8½	*8	1:16
9%	*8	1:16
103/4	8	1:16
11 ¾	8	1:16
13¾	8	1:16
16	8	1:16
18 %	8	1:16
20	*8	1:16

Note: \*Short and long

#### **BUTTRESS CSG**

Buttress Casing Thread Gauges Thread angle : 3° x 10°

Size	T.P.I.	Taper
41/2	5	1:16
5	5	1:16
51/2	5	1:16
6%	5	1:16
7	5	1:16
71/8	5 5	1:16
8%	5	1:16
9%	5	1:16
10¾	5	1:16
11 %	5	1:16
13¾	5	1:16
16	5	1:12
18%	5 5	1:12
20	5	1:12

#### **TBG**

Non-Upset Tubing Thread Gauges Thread angle 60°

Size	T.P.I.	Taper
1.050	10	1:16
1.315	10	1:16
1.660	10	1:16
1.900	10	1:16
2 %	10	1:16
2½ 3½	10	1:16
31/2	10	1:16
4	8	1:16
41/2	8	1:16

#### **UP TBG**

External-Upset Tubing Thread Gauges Thread angle 60°

Size	T.P.I.	Taper
1.050	10	1:16
1.315	10	1:16
1.660	10	1:16
1.900	10	1:16
23/6	8	1:16
27/8	8	1:16
31/2	8	1 : 16
4	8	1:16
41/2	8	1:16

#### Ex. Li. Casing

Extreme-Line Casing Thread & Seal Gauges Thread angle :  $6^{\circ}$  x  $6^{\circ}$ 

Size	T.P.I.	Taper
5	6	1:8
51/2	6	1:8
5½ 6%	6	1:8
7	6	1:8
7%	6	1:8
7 % 8 % 9 %	5	1:9.6
9 1/B	5	1:9.6
103/4	5	1:9.6

Note: Taper of seal = 1:6

#### **API SPEC. 7-2 (Rotary Shouldered Connections)**

#### NC

Number Style Thread angle 60°

Size	T.P.I.	Taper
NC 23	4	1:6
NC 26	4	1:6
NC 31	4	1:6
NC 35	4	1:6
NC 38	4	1:6
NC 40	4	1:6
NC 44	4	1:6
NC 46	4	1:6
NC 50	4	1:6
NC 56	4	1:4
NC 61	4	1:4
NC 70	4	1:4
NC 77	4	1:4

#### REG

Regular Style (Right or left hand) Thread angle 60°

Size	T.P.I.	Taper
1	6	1:8
11/2	6	1:8
23/8	5	1:4
21/8	5	1:4
2½ 3½ 4½	5	1:4
41/2	5	1:4
51/2	4	1:4
65/8	4	1:6
75/8	4	1:4
85/a	4	1:4

#### FH

Full-hole Style Thread angle 60°

Size	T.P.I.	Taper
3 1/2	5	1:4
4	4	1:6
4 1/2	5	1:4
5 1/2	4	1:6
6 1/a	4	1:6

#### IF

Internal-flush Style Thread angle 60°

Size	T.P.I.	Taper
2 3/8	4	1:6
2 1/8	4	1:6
3 1/2	4	1:6
4	4	1:6
41/2	4	1:6
5 1/2	4	1:6